

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/27/2024

Submitted Date:

09/27/2024

Document Number:

716200712**FIELD INSPECTION FORM**Loc ID 431896 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442949	TANK BATTERY	AC	08/21/2015		-	USA FED TANK BATTERY 29N-36HZ	AO

General Comment:

This is a routine Battery audit.

Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared with crude oil tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210 Bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared with crude oil tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.178530,-104.729610
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

