

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Photo # 2428 From entrance to location




Photo # 2429 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Photo # 2430 Location



Photo # 2431 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Photo # 2432 Location



Photo # 2433 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Photo # 2434 Location



Photo # 2435 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486




Photo # 2436 Location



Photo # 2437 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Mar 25, 2024 at 9:34:34 AM
CO



Sep 26, 2024 at 1:36:08 PM
CO

Photo # 1087 From inspection 708903385 conducted on 03/25/2024 Stored equipment/supplies in the interim area

Photo # 2438 Stored equipment/supplies in the interim area

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Photo # 1088 From inspection 708903385 conducted on 03/25/2024 Stored vehicles in the interim area & partially in ditch/Stormwater BMP

Photo # 2439 Stored vehicles in the interim area & partially in ditch/Stormwater BMP

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Photo # 1089 From inspection 708903385 conducted on 03/25/2024 Stored vehicles in the interim area & partially in ditch/Stormwater BMP

Photo # 2440 Stored vehicles in the interim area & partially in ditch/Stormwater BMP

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Photo # 1090 From inspection 708903385 conducted on 03/25/2024 Stored equipment/supplies on location



Photo # 2441 Stored equipment/supplies on location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Photo # 1091 From inspection 708903385 conducted on 03/25/2024 Stored equipment/supplies on location

Photo # 2442 Stored equipment/supplies on location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 335486



Photo # 1092 From inspection 708903385 conducted on 03/25/2024 Stored equipment/supplies on location

Photo # 2443 Stored equipment/supplies on location