

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 33-36 Pad

Location ID: 335050



Photo # 2112 From entrance to location



Photo # 2113 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 33-36 Pad

Location ID: 335050



Photo # 2114 Location



Photo # 2115 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 33-36 Pad

Location ID: 335050



Photo # 2116 Location



Photo # 2117 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 33-36 Pad

Location ID: 335050



Photo # 2118 Location



Photo # 2119 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 33-36 Pad

Location ID: 335050



Photo # 2120 Location



Photo # 2121 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 33-36 Pad

Location ID: 335050



Photo # 2122 Location



Photo # 2123 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 33-36 Pad

Location ID: 335050



Photo # 2124 Location



Photo # 2125 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 33-36 Pad

Location ID: 335050



Photo # 2126 Location



Photo # 2127 Tank lacks required labeling





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 33-36 Pad

Location ID: 335050



Photo # 2128 Staining near wellhead



Photo # 2129 Staining near wellhead



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 33-36 Pad

Location ID: 335050



Photo # 2130 Stored equipment & misc in the interim area



Photo # 2131 Stored trailer & misc on location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 33-36 Pad

Location ID: 335050



Photo # 2132 Stored trailers & tractor on location



Photo # 2133 Stored trailer, boat & misc in the interim area



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 33-36 Pad

Location ID: 335050



**Photo # 2134 Stored lumber & misc in the interim area**



**Photo # 2135 Stored fence posts, lumber & misc in interim area**