

Inspection Photos
Location Name: VIEFHAUS-65N63W/29NESE
Location #: 306735



Photo #1
Viefhaus 43-29U (123-25173) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 125 yds.



Photo #2
Viefhaus 43-29U Battery site
Abandoned: ALL Equipment Removed
Plugged & Abandoned | PA (1-Well)

