

**Operator: CPR**

**Location Name: Bear 3-65 22-23**

**Loc ID: 449179**

**Inspection: 713900906**



Exhibit A



Exhibit B



Exhibit C





Exhibit D



Exhibit E



**Exhibit F**

**CA:** During inspection it was observed that a wildlife screen for a stack on production equipment was no longer functioning. See inspection photos for details. Install wildlife screen per Rule 608.b.(7).

**CA Resolution:** Operator has appropriately installed wildlife protection netting to comply with Rule 608.b.(7).

**CA:** During inspection of the location multiple violations were observed; 1. Wildlife Protection devices (netting) have not been installed correctly for secondary containment BMP's on two different tanks. 2. The incorrectly installed netting on one Tank resulted in a wildlife mortality. See inspection photos for details. Comply with Rule 902.b to install wildlife protection equipment for secondary containments and remove and properly dispose fluids from within the secondary containment.

**CA Resolution:** Operator has appropriately installed wildlife protection netting to comply with Rule 902.b.