

Inspection Photos
Location Name: State 13-36
API Number: 125-06323



1. Well sign at well location.



2. View of wellhead. Active release at time of inspection.

Inspection Photos
Location Name: State 13-36
API Number: 125-06323



3. Unused equipment and production related debris inside well fencing.



4. Stained soil at Pump Jack gear box.

Inspection Photos
Location Name: State 13-36
API Number: 125-06323



5. Well location overview.



6. Well sign at remote metering location.

Inspection Photos
Location Name: State 13-36
API Number: 125-06323



7. Gas meter inside meter shed.



8. Damaged meter shed roof.

Inspection Photos
Location Name: State 13-36
API Number: 125-06323



9. Damaged meter shed door.



10. Remote metering location overview.