

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/26N-795

Location ID: 334128

Date: 9/26/2024



North End of Location – Photo #03759



Wellheads – Photo #03760

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/26N-795

Location ID: 334128

Date: 9/26/2024



Separators – Photo #03765



Tank Battery – Photo #03768

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/26N-795

Location ID: 334128

Date: 9/26/2024



ECD – Photo #03766



Damaged Barbed Wire Fencing – Photo #03762

Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/26N-795

Location ID: 334128

Date: 9/26/2024



Damaged Barbed Wire Fencing – Photo #03764



Damaged Barbed Wire Fencing – Photo #03767