


Inspection Photos
Location Name: Varra 5-1 Pad
Location ID: 430411



Lease road entrance sign



Production facility

Inspection Photos
Location Name: Varra 5-1 Pad
Location ID: 430411



Energy & Carbon Management Commission
40.51272, -104.92176, 1472.0m, 25°
10/01/2024 11:50:14

400 bbl produced water tank capacity and contents placard



Energy & Carbon Management Commission
40.51272, -104.92183, 1472.5m, 15°
10/01/2024 11:50:25

400 bbl crude oil tank capacity and contents placard

Inspection Photos
Location Name: Varra 5-1 Pad
Location ID: 430411



Large ECD unit



Air inlet access

Inspection Photos
Location Name: Varra 5-1 Pad
Location ID: 430411



Energy & Carbon Management Commission
40.51258, -104.92274, 1472.2m, 355°
10/01/2024 12:02:17

Air inlet access



Energy & Carbon Management Commission
40.51287, -104.92297, 1468.9m, 10°
10/01/2024 12:07:03

Separator #10 burner access