

Final Reclamation and Stormwater Inspection

Date: 09/27/2024

Operator: PDC ENERGY INC - 69175

Location ID: 331006

Inspection Document #: 708201642

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Hankins-65N67W 22NESE

Location ID: 331006



Photo 1. Facing north. Operator has performed final reclamation activities and has removed all surface equipment (flowline riser) that was previously documented in FIR (doc #708201267). The former tank battery is within recently harvested/fallow cropland; therefore, a future inspection will be conducted during the active crop growing season to ensure vegetative compliance.



Inspection Photos
Location Name: Hankins-65N67W 22NESE
Location ID: 331006



Photo 2. Facing east; see comments in Photo 1.

Inspection Photos
Location Name: Hankins-65N67W 22NESE
Location ID: 331006



Photo 3. Facing south; see comments in Photo 1.

Inspection Photos

Location Name: Hankins-65N67W 22NESE

Location ID: 331006



Photo 4. Facing west; see comments in Photo 1.