

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/19NESE

Location ID: 335031

Date: 9/26/2024



Sep 26, 2024 at 13:13:35  
Parachute CO 81635  
United States

Location Entrance – Photo #03787



Sep 26, 2024 at 13:16:44  
Parachute CO 81635  
United States

Wellheads/Weeds – Photo #03799



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/19NESE

Location ID: 335031

Date: 9/26/2024



Sep 26, 2024 at 13:17:16  
Parachute CO 81635  
United States

Separators – Photo #03800



Sep 26, 2024 at 13:14:20  
Parachute CO 81635  
United States

Tank Battery – Photo #03789





## Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/19NESE

Location ID: 335031

Date: 9/26/2024



Gas Meter – Photo #03801



Weeds Across Location – Photo #03797



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL-67S95W/19NESE

Location ID: 335031

Date: 9/26/2024



Weeds Across Location – Photo #03798



Open-Ended Tubing – Photo #03790