

Inspection Photos

API: 071-06468

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 10/1/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the wellsite.



Inspection Photos



Photo 2. Well sign is posted at meter shed..



Inspection Photos



Photo 3. Facing southeast along the fill slope which appears to be stabilized.

