

Inspection Photos

API: 071-06425

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 10/1/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the wellsite..



Inspection Photos



Photo 2. Well sign is posted at meter shed..



Inspection Photos



Photo 3. Facing southeast along the fill slope which appears to be stabilized.



Inspection Photos



Photo 4. There is a plastic pipe and a steel rod at the bottom of the fill slope that needs to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06425 | Date: 10/1/2024