

Inspection Photos

API: 071-09177

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 10/1/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest at the beginning of the former access road.



Inspection Photos



Photo 2. Facing northwest along the canyon drainage.



Inspection Photos



Photo 3. Facing northwest along the reclaimed access road.



Inspection Photos



Photo 4. Facing northwest toward the reclaimed location. Perennial vegetation is progressing.

