

Final Reclamation Inspection

Date: 9/27/24

Operator: Noble Energy Inc - 100322

Location ID: 419226

Inspection Document #: 713901028

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: FIVE RIVERS K 03-23
Location ID: 419226



Photo 1. The photo was taken at the well location facing North. The photo illustrates the wells were never drilled.



Photo 2. The photo was taken at the well location facing East. Refer to the comment for photo 1.

Inspection Photos
Location Name: FIVE RIVERS K 03-23
Location ID: 419226



Photo 3. The photo was taken at the well location facing South.
Refer to the comment for photo 1.



Photo 4. The photo was taken at the well location facing West.
Refer to the comment for photo 1.

Inspection Photos
Location Name: FIVE RIVERS K 03-23
Location ID: 419226



Photo 5. The photo was taken at the well location facing South. The photo illustrates the area where tank facility was located. The tank battery area has not yet met standards.