

Inspection Photos
Location Name: Crossland 1-1
API Number: 125-08769



1. Well sign at well location.



2. View of wellhead. Note vegetation. White PVC pipe is visible center of frame along the well sign leg.

Inspection Photos
Location Name: Crossland 1-1
API Number: 125-08769



3. Vertical separator inside separator shed.



4. Gas meter inside meter shed.

Inspection Photos
Location Name: Crossland 1-1
API Number: 125-08769



5. View of produced water tank.



6. Location overview.