

Inspection Photos

Location: QB ENERGY P6-11-36 PAD

Location ID: 418691

Date: 9/30/2024



Entrance to location - Photo #06598



Location - Photo #06629

Inspection Photos

Location: QB ENERGY P6-11-36 PAD

Location ID: 418691

Date: 9/30/2024



Location - Photo #06599

Location - Photo #06600

Inspection Photos
Location: QB ENERGY P6-11-36 PAD
Location ID: 418691
Date: 9/30/2024



Sep 30, 2024 at 4:36:48 PM
+39.485241,-108.174506 ±4.72m
Parachute



Sep 30, 2024 at 4:45:50 PM
+39.485435,-108.174336 ±4.72m
Parachute

Location - Photo #06613

Location - Photo #06627

Inspection Photos

Location: QB ENERGY P6-11-36 PAD

Location ID: 418691

Date: 9/30/2024



Location - Photo #06647

SE corner of location - Photo #06656

Inspection Photos

Location: QB ENERGY P6-11-36 PAD

Location ID: 418691

Date: 9/30/2024



Failure to maintain chemical BMP/chemical tank containment $\frac{3}{4}$ full of fluid - Photo #06665



Loose barbed wire/wildlife hazard - Photo #06625

Inspection Photos

Location: QB ENERGY P6-11-36 PAD

Location ID: 418691

Date: 9/30/2024



Loose barbed wire/wildlife hazard - Photo #06626

Open separator doors/wildlife hazard - Photo #06614

Inspection Photos

Location: QB ENERGY P6-11-36 PAD

Location ID: 418691

Date: 9/30/2024



Sep 30, 2024 at 4:52:39 PM
+39.485489,-108.174139 ±4.73m
Parachute



Sep 30, 2024 at 4:52:50 PM
+39.485489,-108.174139 ±4.73m
Parachute

Holes in secondary containment liner - Photo #06639

Holes in secondary containment liner - Photo #06640

Inspection Photos

Location: QB ENERGY P6-11-36 PAD

Location ID: 418691

Date: 9/30/2024



Holes in secondary containment liner - Photo #06641

Debris - Photo #06603

Inspection Photos

Location: QB ENERGY P6-11-36 PAD

Location ID: 418691

Date: 9/30/2024



Debris - Photo #06604

Debris - Photo #06608

Inspection Photos

Location: QB ENERGY P6-11-36 PAD

Location ID: 418691

Date: 9/30/2024



Sep 30, 2024 at 4:34:15 PM
+39.484909, -108.174778 ±4.71m
Parachute



Sep 30, 2024 at 4:40:56 PM
+39.485237, -108.174385 ±4.73m

Debris - Photo #06610

Debris - Photo #06620

Inspection Photos

Location: QB ENERGY P6-11-36 PAD

Location ID: 418691

Date: 9/30/2024



Sep 30, 2024 at 4:51:08 PM
+39.485434, -108.174128 ±4.73m
Parachute



Sep 30, 2024 at 4:52:17 PM
+39.485432, -108.174256 ±4.76m
Parachute

Debris - Photo #06633

Debris - Photo #06637

Inspection Photos

Location: QB ENERGY P6-11-36 PAD

Location ID: 418691

Date: 9/30/2024



Debris - Photo #06664

Unmarked deadman - Photo #06658

Inspection Photos

Location: QB ENERGY P6-11-36 PAD

Location ID: 418691

Date: 9/30/2024



Unmarked deadman - Photo #06660

Unmarked deadman - Photo #06662