

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403946302

Date Received:
10/04/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10671
Name of Operator: EDGE ENERGY II LLC
Address: 600 12TH STREET SUITE 115
City: GOLDEN State: CO Zip: 80401
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Kelsi Welch</u>		<u>Kelsi.welch@iptwell.com</u>
<u>Ben Turner</u>		<u>bturner@edgeenergy1.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 693700917
Inspection Date: 01/24/2022 FIR Submit Date: 01/25/2022 FIR Status: _____

Inspected Operator Information:

Company Name: EDGE ENERGY II LLC Company Number: 10671
Address: 600 12TH STREET SUITE 115
City: GOLDEN State: CO Zip: 80401

LOCATION - Location ID: 422460

Location Name: Rawhide Flats 10-68-16 Number: 1B County: _____
Qtrqtr: NENE Sec: 16 Twp: 10N Range: 68W Meridian: 6
Latitude: 40.839661 Longitude: -105.002416

FACILITY - API Number: 05-069-00 Facility ID: 422460

Facility Name: Rawhide Flats 10-68-16 Number: 1B
Qtrqtr: NENE Sec: 16 Twp: 10N Range: 68W Meridian: 6
Latitude: 40.839661 Longitude: -105.002416

CORRECTIVE ACTIONS:

1 CA# 159335

Corrective Action: Submit a Form 42 - Abandonment of Flowlines within 90 days. Contact Engineering Integrity Engineer for guidance on submitting Form 43 Abandonment Notification after the fact. Date: 04/24/2022

Response: CA COMPLETED Date of Completion: 03/24/2022

Operator Comment: Please see approved Form 42 doc #402994839.

ECMC Decision: _____

ECMC
Representative:

2 CA# 159336

Corrective Action: Form 27 must be resubmitted with a proposal indicating planned soil screening and soil sample locations, proposed soil sample analysis, and site map illustrating equipment locations and planned soil sample locations. Operator should refer to the to Rule 911.a.(4) - Oil and Gas Facility Closure Guidance Document and Rule 911.a.(4) checklists, as well as 915.e.(2) - Soil Sampling and Analysis Guidance Document. Operator shall include a schedule for sampling and followup reporting.

Date: 02/08/2022

At a minimum samples for laboratory analysis are required adjacent the well at base of excavation, beneath former flowline risers, beneath heater treater, beneath AST footprint (beneath the liner once removed). Minimum required soil analysis includes the following Table 915-1 Contaminants of Concern: TPH (C6-C36), benzene, toluene, ethylbenzene, total xylenes, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene and soil suitability for reclamation parameters: electrical conductivity (EC), Sodium Adsorption Ratio (SAR), pH, and boron.

If impacts are observed Operator shall analyze soil samples for complete Table 915-1 Contaminants of Concern.

Corrective action date is date to resubmit Form 27 Workplan.

Response: CA COMPLETED

Date of Completion: 02/04/2022

Operator Comment: Form 27-I doc #402914860 was submitted 2/4/2022. Supplemental Form 27s doc #'s 403007496 & 403146688 were submitted with the soil sample analysis results.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: This is a retroactive submission to formally resolve the subject inspection and for compliance with Rule 210.b.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kelsi Welch

Signed: _____

Title: Permitting & Compliance

Date: 10/4/2024 9:07:18 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files