

## Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NENW

Location ID: 324326

Date: 9/30/2024



Photo # 6509 Entrance to location



Photo # 6522 Location

## Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NENW

Location ID: 324326

Date: 9/30/2024



Photo # 6510 Location



Photo # 6514 Location

## Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NENW

Location ID: 324326

Date: 9/30/2024



Photo # 6519 Location



Photo # 6530 SW corner of location

## Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NENW

Location ID: 324326

Date: 9/30/2024



Photo # 6531 NW corner of location



Photo # 6535 Unmarked deadman

## Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1NENW

Location ID: 324326

Date: 9/30/2024



Photo # 6536 Unmarked deadman



Photo # 6525 Debris