

Inspection Photos

Location: QB ENERGY PUCKETT 66S97W/36NENW

Location ID: 324333

Date: 9/30/2024



Sep 30, 2024 at 5:13:11 PM
+39.485820,-108.171509 ±4.73m
Parachute



Sep 30, 2024 at 5:20:59 PM
+39.485934,-108.171303 ±4.73m
Parachute

Photo # 6668 Entrance to location

Photo # 6683 Location

Inspection Photos

Location: QB ENERGY PUCKETT 66S97W/36NENW

Location ID: 324333

Date: 9/30/2024




Photo #6669 Location

Photo # 6679 Location

Inspection Photos

Location: QB ENERGY PUCKETT 66S97W/36NENW

Location ID: 324333

Date: 9/30/2024



Photo # 6682 Location

Photo # 6688 NE corner of location

Inspection Photos

Location: QB ENERGY PUCKETT 66S97W/36NENW

Location ID: 324333

Date: 9/30/2024



Photo # 6689 SE corner of location



Photo # 6673 Debris

Inspection Photos

Location: QB ENERGY PUCKETT 66S97W/36NENW

Location ID: 324333

Date: 9/30/2024



Photo # 6676 Debris

Photo # 6692 Unmarked deadman