

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/26-6 PAD

Location ID: 311750

Date: 10/1/2024



Photo # 6808 Entrance to location



Photo # 6836 Location

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/26-6 PAD

Location ID: 311750

Date: 10/1/2024



Photo # 6809 Location



Photo # 6811 Location

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/26-6 PAD

Location ID: 311750

Date: 10/1/2024



Photo # 6817 Location



Photo # 6820 Location

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/26-6 PAD

Location ID: 311750

Date: 10/1/2024



Photo # 6822 Location



Photo # 6823 Location

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/26-6 PAD

Location ID: 311750

Date: 10/1/2024



Photo # 6834 Location



Photo # 6835 Location

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/26-6 PAD

Location ID: 311750

Date: 10/1/2024



Photo # 6842 SE corner of location



Photo # 6843 NE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/26-6 PAD

Location ID: 311750

Date: 10/1/2024



Photo # 6846 SW corner of location



Photo # 6828 PRV vent line does not comply with CECMC pressure safety rules

Inspection Photos

Location: LARAMIE ENERGY LLC HELLS GULCH FEDERAL/26-6 PAD

Location ID: 311750

Date: 10/1/2024



Photo # 6819 Debris



Photo # 6841 Debris