

# Inspection Photos

October 3rd, 2024

Operator: Robert L. Bayless Producer - 6720

Location ID: 313594

Inspection Document #: 714001304

Montezuma County, CO

Township: NWNW 15 35N 20W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: North Mail Trail 1  
Location ID: 313594

10/3/24  
+37.295458,-109.041826  
28° NE



Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos  
Location Name: North Mail Trail 1  
Location ID: 313594



**Photo 2.** Stained soils observed at pump jack muffler.



Inspection Photos  
Location Name: North Mail Trail 1  
Location ID: 313594

10/3/24  
+37.295912,-109.041548  
352° N



**Photo 3.** Engine oil barrel in the northern portion of the disturbance with no secondary containment.

Inspection Photos  
Location Name: North Mail Trail 1  
Location ID: 313594

10/3/24  
+37.295917,-109.041414  
169° S



**Photo 4.** View of the eastern interim reclamation area facing south.

Inspection Photos  
Location Name: North Mail Trail 1  
Location ID: 313594

10/3/24  
+37.295917,-109.041414  
73° E



**Photo 5.** Reference area comprised of Sagebrush, Broom snakeweed and Indian ricegrass.