

Inspection Photos

October 3rd, 2024

Operator: Robert L. Bayless Producer - 6720

Location ID: 313588

Inspection Document #: 714001308

Montezuma County, CO

Township: NWSW 23 35N 20W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: North Mail Trail 2
Location ID: 313588

10/3/24
+37.276860,-109.025220
300° NW



Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos
Location Name: North Mail Trail 2
Location ID: 313588

10/3/24
+37.275831,-109.026234
112° E



Inspection Photos
Location Name: North Mail Trail 2
Location ID: 313588

10/3/24
+37.275831,-109.026234
221° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Reference area comprised of Sagebrush, Broom snakeweed and Indian ricegrass.

API #: 083-06609