

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403944212

Date Received:

10/03/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 693904241

Inspection Date: 02/18/2022

FIR Submit Date: 02/22/2022

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 334177

Location Name: NEIL GAS UNIT 34-13-M34N8W Number: 13SWSE County: LA PLATA

Qtrqr: SWSE Sec: 13 Twp: 34N Range: 8W Meridian: M

Latitude: 37.186760 Longitude: -107.665830

FACILITY - API Number: 05-067-00 Facility ID: 285294

Facility Name: NEIL 34-13 Number: 3

Qtrqr: SWSE Sec: 13 Twp: 34N Range: 8W Meridian: M

Latitude: 37.186760 Longitude: -107.665830

CORRECTIVE ACTIONS:

1 CA# 159805

Corrective Action: -Remove and properly dispose of wire debris within the western project area by 3/30/2022.

Date: 03/30/2022

Response: CA COMPLETED

Date of Completion: 10/01/2024

Operator
Comment:

Debris and gravel piles removed from western edge of location.

ECMC Decision: _____

Date: 10/3/2024 9:19:45 AM

Page 2 of 2