

# Inspection Photos

Loc: 324809

Operator: WESTERN OPERATING COMPANY

Inspection Date: 10/3/2024

County: KIOWA



## Inspection Photos



**Photo 1.** Facing northeast at the access road toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 324809 | Date: 10/3/2024

## Inspection Photos



**Photo 2.** Facing west at the backside of the tank battery. The tank on the left appears to be rusted out on the bottom and the outlet at red arrow has oil stained soils.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 324809 | Date: 10/3/2024



## Inspection Photos



**Photo 3.** Facing southeast at the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc: 324809 | Date: 10/3/2024