

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/27NWNW

Location ID: 335978

Date: 10/8/2024



Location Entrance – Photo #03999



Wellheads – Photo #04001

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/27NWNW

Location ID: 335978

Date: 10/8/2024



Gas Meters – Photo #04003



Gas Lift – Photo #04008

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/27NWNW

Location ID: 335978

Date: 10/8/2024



Tank Battery – Photo #04004



Peeling Paint/Corrosion – Photo #04005