

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 237-28 Pad

Location ID: 335130



Photo # 3977 From entrance to location



Photo # 3978 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 237-28 Pad

Location ID: 335130



Photo # 3979 Location



Photo # 3980 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 237-28 Pad

Location ID: 335130



Photo # 3981 Location



Photo # 3982 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 237-28 Pad

Location ID: 335130



Photo # 3983 Production tank labeled inaccurately/capacity incorrect



Photo # 3984 Correct tank capacity