

Inspection Photos

Location Name: QB Energy HMU 6-11 (J6SE) Pad

Location #: 324343



Photo # 4280 From entrance to location



Photo # 4281 Location



Inspection Photos
Location Name: QB Energy HMU 6-11 (J6SE) Pad
Location #: 324343



Photo # 4282 Location



Photo # 4283 Location

Inspection Photos
Location Name: QB Energy HMU 6-11 (J6SE) Pad
Location #: 324343



Photo # 8602 From inspection 708904507 conducted on 09/06/2024 Wellhead lacks required signage/does not comply with CECMC rules



Photo # 4284 Wellhead lacks required signage/does not comply with CECMC rules