

## State of Colorado

## Energy &amp; Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403946488

Date Received:

10/10/2024

Spill report taken by:

NEIDEL, KRIS

Spill/Release Point ID:

487954

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECMC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

## OPERATOR INFORMATION

Name of Operator: SCOUT ENERGY MANAGEMENT LLC	Operator No: 10779	<b>Phone Numbers</b>
Address: 13800 MONTFORT DRIVE SUITE 100		Phone: (970) 551-8320
City: DALLAS	State: TX	Zip: 75240
Contact Person: Cody Christian		Mobile: (970) 902-0518
		Email: cody.christian@scoutep.com

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

## INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 403928689

Initial Report Date: 09/20/2024	Date of Discovery: 09/18/2024	Spill Type: Recent Spill
---------------------------------	-------------------------------	--------------------------

**Spill/Release Point Location:**

QTRQTR SWNW SEC 23 TWP 2N RNG 103W MERIDIAN 6

Latitude: 40.132216 Longitude: -108.932992

Municipality (if within municipal boundaries): County: RIO BLANCO

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

☒ Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

**Reference Location:**

Facility Type: WELL SITE ☐ Facility/Location ID No

Spill/Release Point Name: AC McLaughlin 65X ☒ Well API No. (Only if the reference facility is well) 05-103-07718

☐ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=1 and <5	Estimated Condensate Spill Volume(bbl): 0
Estimated Flow Back Fluid Spill Volume(bbl): 0	Estimated Produced Water Spill Volume(bbl): >=5 and <100
Estimated Other E&P Waste Spill Volume(bbl): 0	Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: NON-CROP LANDOther(Specify):

Weather Condition: Sunny and 75 degrees

Surface Owner: FEDERALOther(Specify):

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On September 18, about 2:30 PM there was an on location well head line leak discovered on AC McLaughlin 65x after investigating a low flowline pressure alarm. Produced injection water and oil were released to ground. All fluids stayed on well pad location. Once it was discovered the operator immediately shut the well in and contained leak on location. All proper notifications were made, repair and clean up plans were made. Spill area washed with fresh clean water from water plant.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
9/18/2024	Entrada	Tim Dobransky	-	Emailed
9/18/2024	CPW	Garrett Smith	-	Emailed
9/18/2024	Rio Blanco County	Edward Smercina	-	Emailed
9/18/2024	BLM	Tim Barrett	-	Emailed
9/18/2024	ECMC	Kris Neidel	970-846-5097	Left voice message

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

- ☐ No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.
- Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_
- Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_
- Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_
- ☐ Yes Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.
- ☐ Yes Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.
- ☐ No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak
- Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)
- Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_
- Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_
- Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_
- Was there damage during excavation? \_\_\_\_\_
- Was CO 811 notified prior to excavation? \_\_\_\_\_
- ☐ No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.
- Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_

No	Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:  <input type="checkbox"/> The presence of free product or hydrocarbon sheen Surface Water <input type="checkbox"/> The presence of free product or hydrocarbon sheen on Groundwater <input type="checkbox"/> The presence of contaminated soil in contact with Groundwater <input type="checkbox"/> The presence of contaminated soil in contact with Surface water
No	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight's from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.  <input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

## SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 10/10/2024		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL		1	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER		20	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	80	65	<input type="checkbox"/>

specify: Fresh clean water from water plant used to water wash spill area.

Was spill/release completely contained within berms or secondary containment? YES Was an Emergency Pit constructed? NO

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

**A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit**

Impacted Media (Check all that apply) ☒ Soil ☐ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 60 Width of Impact (feet): 12

Depth of Impact (feet BGS): 2 Depth of Impact (inches BGS):

How was extent determined?

Measuring tape and wheel.

Soil/Geology Description:

High clay.

Depth to Groundwater (feet BGS) 3320 Number Water Wells within 1/2 mile radius: 0

If less than 1 mile, distance in feet to nearest

Water Well	None <input checked="" type="checkbox"/>	Surface Water	558	None <input type="checkbox"/>
Wetlands	None <input checked="" type="checkbox"/>	Springs		None <input checked="" type="checkbox"/>
Livestock	None <input checked="" type="checkbox"/>	Occupied Building		None <input checked="" type="checkbox"/>

Additional Spill Details Not Provided Above:

All Fluids stayed on well pad location. All distances above were obtained from the COGCC online GIS system. Depth of impact (line failure) was approximately 2 feet below grade. A below the pipe soil sample will be taken to show vertical delineation. Additional soil samples will also be taken along spill path and areas, all liquids were removed with a vac-truck. Spill area washed with fresh clean water from water plant.

## CORRECTIVE ACTIONS

#1 Supplemental Report Date: 10/10/2024

Root Cause of Spill/Release Corrosion

Other (specify)

Type of Equipment at Point of Spill/Release: Wellhead Line

If "Other" selected above, specify or describe here:

Describe Incident & Root Cause (include specific equipment and point of failure)

Production flow line off of well head leak due to corrosion.

Describe measures taken to prevent the problem(s) from reoccurring:

Replace with carbon coated stainless.

Volume of Soil Excavated (cubic yards): 0

Disposition of Excavated Soil (attach documentation)

☐ Offsite Disposal

☐ Onsite Treatment

☐ Other (specify)

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure: ☐ Corrective Actions Completed (documentation attached, check all that apply)

☐ Horizontal and Vertical extents of impacts have been delineated.

☐ Documentation of compliance with Table 915-1 is attached.

☐ All E&P Waste has been properly treated or disposed.

☐ Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: \_\_\_\_\_

☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

## OPERATOR COMMENTS:

This is to address document number 701104077. To clarify, the location of the leak occurred to an on-location line between the well head and the riser. Therefore did not occur on a registered off-location flowline.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Cody Christian

Title: HSE Coordinator Date: 10/10/2024 Email: cody.christian@scoutep.com

<u>COA Type</u>	<u>Description</u>
0 COA	

#### ATTACHMENT LIST

<u>Att Doc Num</u>	<u>Name</u>
403953516	AERIAL IMAGE
403953543	PHOTO DOCUMENTATION

Total Attach: 2 Files

#### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	Was the failed line below ground? How deep, do we know where (lat, long, distance from wellhead, etc)	10/08/2024

Total: 1 comment(s)