

# Inspection Photos

10/08/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 335096

**Inspection Doc:** 696206361

Garfield County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335096



**Photo 1:** Photos 1-2 taken from the east end of the Location. Photos provide an overview from south, southwest northwest to north.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335096



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335096



**Photo 3:** Cellar at well has not been covered, or cellar has not been backfilled. Wildlife mortality observed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335096



October 8, 2024

**Photo 4:** Line at tank missing cap/plug.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335096



October 8, 2024

**Photo 5:** BMPs to stabilize the working pad surface, as well as to minimize tracking and off-site sediment transport during wet conditions show sign of disrepair and/or do not appear sufficient; gravel is thin throughout pad and compaction is failing. No other BMPs to minimize tracking/sed. transport observed. Maintenance advised.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335096



**Photo 6:** Photos examples showing interim areas of the Location.