

Inspection Photos

Loc: 322266

Operator: **JAVERNICK OIL**

Inspection Date: 10/9/2024

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north at the abandoned wellsite. The site has been seeded and straw mulched. There are undesirable weeds shown at red arrow that should be controlled.



Inspection Photos



Photo 2. The straw mulch was not crimped and soils may not be still seem compacted. This would impact revegetation.



Inspection Photos



Photo 3. Facing southwest toward the surrounding undisturbed vegetation.

