

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403923644
Receive Date:
09/17/2024

Report taken by:
Kilian Collins

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: NOBLE ENERGY INC	Operator No: 100322	Phone Numbers Phone: (970) 730-7281 Mobile: ()
Address: 1099 18TH STREET SUITE 1500		
City: DENVER	State: CO	Zip: 80202
Contact Person: Dan Peterson	Email: rbueuf27@chevron.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 20156 Initial Form 27 Document #: 402816518

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

Yes Multiple Facilities

Facility Type: TANK BATTERY	Facility ID: 329417	API #: _____	County Name: WELD
Facility Name: FRANK-64N64W 12NWNE	Latitude: 40.331823	Longitude: -104.496621	
** correct Lat/Long if needed: Latitude: 40.332363		Longitude: -104.489845	
QtrQtr: NWNE	Sec: 12	Twp: 4N	Range: 64W Meridian: 6 Sensitive Area? Yes
Facility Type: SPILL OR RELEASE	Facility ID: 481479	API #: _____	County Name: WELD
Facility Name: Frank 1, 12-02, 7-4	Latitude: 40.332204	Longitude: -104.489884	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: NENE	Sec: 12	Twp: 4N	Range: 64W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SW _____

Most Sensitive Adjacent Land Use crop _____

Is domestic water well within 1/4 mile? Yes _____

Is surface water within 1/4 mile? Yes _____

Is groundwater less than 20 feet below ground surface? No _____

Other Potential Receptors within 1/4 mile

HPH: none, surface ponds ~0.13 mi NE, Latham Ditch ~0.20 mi SW, no buildings

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input checked="" type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input checked="" type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	GROUNDWATER	NA	laboratory analysis
Yes	SOILS	20' X 20' X 10' BGS	laboratory analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

A site investigation was conducted pursuant to ECMC Rule 911 at the FRANK T4N-R64W-S12 L02 Tank Battery location.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Ten (10) grab confirmation soil samples were collected from the partially-buried produced water vessel excavation, beneath the above-ground oil tank, and at the separator. Soil samples were analyzed by a certified laboratory for TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons), organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, and boron. Additionally, one soil sample (FS02@8') was analyzed for metals in soil per ECMC Table 915-1. All samples collected were analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

A total of twenty-five (25) temporary monitoring wells have been installed at the site to delineate dissolved phase impacts. The existing monitoring wells will continue to be sampled on a quarterly basis, and analyzed for BTEX, naphthalene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, 1-methylnaphthalene, 2-methylnaphthalene, total dissolved solids (TDS), chloride, and sulfate by a certified laboratory.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Site Assessment activities were conducted from 5/23/2022 to 11/13/2023 to delineate impacted media. Twenty-one soil borings were advanced in the area of potential impacts. BH01 was advanced at the same location as the waste characterization sample (FS02@8') to vertically delineate impacts at that location. BH02 - BH21 were advanced surrounding BH01 to vertically and laterally delineate impacts identified at FS01@6' and FL02@8'. Soil samples were collected and analyzed for TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons), organic compounds and metals in soil per ECMC Table 915-1, EC, SAR, pH, and boron. Based on the data presented, hydrocarbon compounds in exceedance of ECMC Table 915-1 standards have been fully delineated. Each of the 21 soil borings were converted into temporary groundwater monitoring wells to delineate dissolved phase impacts. The existing monitoring wells will continue to be sampled quarterly, as described in the Groundwater Monitoring section.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 99
Number of soil samples exceeding 915-1 66
Was the areal and vertical extent of soil contamination delineated? Yes
Approximate areal extent (square feet) 2100

NA / ND

-- Highest concentration of TPH (mg/kg) 1680
-- Highest concentration of SAR 10.8
BTEX > 915-1 No
Vertical Extent > 915-1 (in feet) 10

Groundwater

Number of groundwater samples collected 14
Was extent of groundwater contaminated delineated? Yes
Depth to groundwater (below ground surface, in feet) 6
Number of groundwater monitoring wells installed 21
Number of groundwater samples exceeding 915-1 1

ND Highest concentration of Benzene (µg/l) _____
ND Highest concentration of Toluene (µg/l) _____
ND Highest concentration of Ethylbenzene (µg/l) _____
ND Highest concentration of Xylene (µg/l) _____
NA Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
 Number of surface water samples exceeding 915-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Twenty-five (25) background soil samples from ten discrete soil boring locations were collected and analyzed for pH, SAR, and ECMC Table 915-1 metals. A detailed discussion of the background sampling results is presented in the second quarter 2024 Supplemental Form 27 (Document No. 403711476).

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?

A supplemental site investigation (SSI) will be completed to horizontally delineate the the elevated SAR results observed in sample locations BH08@6-8' and BH08@9-10', and to vertically and/or horizontally delineate the elevated pH results observed in sample locations BH03@6-8', BH04@15-17', BH18@6-8', BH18@10-12', BH18@15-17', BH19@10-12', BH19@15-17', BH20@6-7', BH21@6-7.5', and BH21@11-12' during the 5/23/2022 to 11/13/2023 site assessment activities. Based on the pH and SAR exceedances identified during the previous site assessment activities, full delineation of hydrocarbon compounds in exceedance of ECMC Table 915-1 standards in both soil and groundwater, and elimination of metals as contaminants of concern, Noble proposes to limit future SSI soil sampling to pH and SAR only. Concurrently with the SSI, additional background soil samples will be collected to determine if elevated pH and SAR results are attributed to native soil conditions at the site. The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27. The proposed soil boring locations are illustrated in Figure 6.

Monitoring wells BH15R - BH17R, BH20, and BH21 were noted as destroyed on arrival during the second quarter 2024 groundwater monitoring event. As such, five additional replacement monitoring wells (BH15R2 - BH17R2, BH20R, and BH21R) will be installed to maintain points-of-compliance (POC) and continue the quarterly monitoring program. The proposed replacement monitoring well locations are illustrated on Figure 5.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Preliminary delineation of the source material was conducted through the environmental site assessments completed on 5/23/2022 to 11/13/2023. The site assessment results, including sample location figures, analytical data tables, and laboratory analytical data, are attached to the second quarter 2024 Supplemental Form 27 (Document No. 403711476). Based on the data presented, hydrocarbon compounds in exceedance of ECMC Table 915-1 standards have been fully delineated. Based on the comparative analysis of metals in the site assessment soil samples to the background soil samples, as described in the aforementioned Supplemental Form 27, metals should not be considered contaminants of concern at the site. Quarterly groundwater monitoring will be continued until four consecutive quarters of compliant groundwater results have been achieved.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

A supplemental site investigation (SSI) will be completed to vertically and horizontally delineate the the elevated pH and SAR results observed during the 5/23/2022 to 11/13/2023 site assessment activities, in accordance with the attached proposed site investigation map, and proposed sampling plan outlined in the Site Investigation Report. The groundwater monitoring wells will continue to be sampled on a quarterly basis to ensure the dissolved phase groundwater plume is stable and decreasing. Based on the latest groundwater monitoring data, provided as an attachment to this Form 27, quarterly groundwater monitoring will be conducted for a minimum of four additional quarters, until constituent concentrations remain in compliance with the applicable groundwater standards for at least four consecutive quarters. Following the additional SSI soil sampling activities outlined in the Site Investigation Report section, the generation of a detailed reclamation plan, and the completion of quarterly groundwater monitoring, Noble will request a No Further Action (NFA) designation for the site.

Soil Remediation Summary

In Situ

Ex Situ

_____ Bioremediation (or enhanced bioremediation)

_____ Excavate and offsite disposal

_____ Chemical oxidation

_____ If Yes: Estimated Volume (Cubic Yards) _____

_____ Air sparge / Soil vapor extraction

_____ Name of Licensed Disposal Facility or ECMC Facility ID # _____

_____ Natural Attenuation

_____ Excavate and onsite remediation

_____ Other _____

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

Yes _____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

A total of twenty-one (21) temporary monitoring wells (BH01 - BH09, BH10R, BH11-BH14, BH15R - BH17R, BH18-BH21) were installed at the site to delineate dissolved phase impacts. The existing monitoring wells will continue to be sampled on a quarterly basis, and analyzed for BTEX, naphthalene, 1,2,4- trimethylbenzene (TMB), 1,3,5-TMB, 1-methylnaphthalene (M), 2-M, total dissolved solids (TDS), chloride, and sulfate until four consecutive quarters of compliant groundwater results has been achieved. Monitoring wells BH15R - BH17R, BH20, and BH21 were noted as destroyed on arrival during the second quarter 2024 groundwater monitoring event.

Third quarter 2024 analytical results indicated that the 1-M concentration was in exceedance of the applicable regulatory standard in monitoring well BH11. Organic compound concentrations were in compliance with the applicable regulatory standards in the remaining 15 sampled monitoring well locations. In addition, inorganic parameters were in compliance with the applicable regulatory standards or within 1.25x the background concentrations of the cross-gradient monitoring well (BH04) in all monitoring well locations.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report
 Other _____

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policy MWZZ 316714) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000 _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No _____

If YES:

- Compliant with Rule 913.h.(1).
- Compliant with Rule 913.h.(2).
- Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim

Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 01/26/2022

Proposed date of completion of Reclamation. 12/31/2026

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 08/04/2021

Actual Spill or Release date, or date of discovery. 01/27/2022

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 01/26/2022

Proposed site investigation commencement. 12/31/2024

Proposed completion of site investigation. 03/31/2025

REMEDIAL ACTION DATES

Proposed start date of Remediation. 12/31/2024

Proposed date of completion of Remediation. 12/31/2026

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

Monitoring wells BH15R - BH17R, BH20, and BH21 were noted as destroyed on arrival during the second quarter 2024 groundwater monitoring event. As such, five additional replacement monitoring wells (BH15R2 - BH17R2, BH20R, and BH21R) will be installed to maintain points-of-compliance (POC) and continue the quarterly monitoring program. The proposed replacement monitoring well locations are illustrated on Figure 5.

Based on soil analytical results, further site investigation activities are required to delineate the remaining pH and SAR exceedances on site. Additional background soil borings will be advanced to continue to assess pH and SAR concentrations in native material on site. The proposed soil boring locations are illustrated on Figure 6.

OPERATOR COMMENT

This Supplemental Form 27 was submitted to summarize quarterly groundwater monitoring and analytical results collected during the third quarter 2024 at the Frank 1, 12-02, 7-4 location.

Third quarter 2024 analytical results indicated that the 1-M concentration was in exceedance of the applicable regulatory standard in monitoring well BH11. Organic compound concentrations were in compliance with the applicable regulatory standards in the remaining 15 sampled monitoring well locations. In addition, inorganic parameters were in compliance with the applicable regulatory standards or within 1.25x the background concentrations of the cross-gradient monitoring well (BH04) in all monitoring well locations.

Monitoring wells BH15R - BH17R, BH20, and BH21 were noted as destroyed on arrival during the second quarter 2024 groundwater monitoring event. As such, five additional replacement monitoring wells (BH15R2 - BH17R2, BH20R, and BH21R) will be installed to maintain points-of-compliance (POC) and continue the quarterly monitoring program. The proposed replacement monitoring well locations are illustrated on Figure 5.

Based on soil analytical results, further site investigation activities are required to delineate the remaining pH and SAR exceedances on site. Additional background soil borings will be advanced to continue to assess pH and SAR concentrations in native material on site. The proposed soil boring locations are illustrated on Figure 6.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Jake Whritenour

Title: Environmental Consultant

Submit Date: 09/17/2024

Email: chevroneform@tasman-geo.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Kilian Collins

Date: 10/14/2024

Remediation Project Number: 20156

COA Type

Description

	Operator shall maintain quarterly reporting for groundwater monitoring.
	ECMC approves timeline for completion of additional site investigation activities. Should the schedule change, Operator shall submit a Supplemental Form 27 with an updated Implementation Schedule at least 14 days in advance per Rule 913.d.(2).
2 COAs	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

403923644	INVESTIGATION/REMEDATION WORKPLAN (SUPPLEMENTAL)
403923742	MONITORING REPORT
403956149	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)