

Final Reclamation and Stormwater Inspection

Date: 10/03/2024

Operator: NOBLE ENERGY INC - 100322

Location ID: 305587

Inspection Document #: 708201685

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: N36 Tank
Location ID: 305587



Photo 1. Facing north at the reclaimed location. It appears that final reclamation activities have been performed as the location has been recontoured and hydroseeded. Undesirable vegetation (russian thistle) remains on the location and will require management.

Inspection Photos
Location Name: N36 Tank
Location ID: 305587



Photo 2. Facing east; see comments in Photo 1. Debris (straw wattles) previously documented appear to have been removed.

Inspection Photos
Location Name: N36 Tank
Location ID: 305587



Photo 3. Facing southeast; see comments in Photo 1.

Inspection Photos
Location Name: N36 Tank
Location ID: 305587



Photo 4. Facing west; see comments in Photo 1.