

Inspection Photos
Location Name: Brophy T E 7
API Number: 125-06202



1. Well sign at well location.



2. View of wellhead. Active release at water lag hammer union.

Inspection Photos
Location Name: Brophy T E 7
API Number: 125-06202



3. View of water leg hammer union.



4. View of water leg hammer union

Inspection Photos
Location Name: Brophy T E 7
API Number: 125-06202



5. Well sign at gas meter run.



6. Gas meter inside shared meter shed.

Inspection Photos
Location Name: Brophy T E 7
API Number: 125-06202



7. Location overview.



8. Location overview.