

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 10/01/2024 Document Number: 403878878

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 10746 Contact Person: Randy Evans Company Name: BLACKROCK ENERGY CORP Phone: (970) 4020418 Address: 242 LINDEN STREET Fax: () City: FORT COLLINS State: CO Zip: 80524 Email: Revans@Wellingtonoperating.com

Identification Information

API Number: 05 - - ECMC Facility ID: 468761 Initial Form 19 or 27 Document number: Facility Name: Injection Plant 1 Facility Number: Facility Type: Location Location QtrQtr: NESW Section: 15 Township: 9N Range: 68W Meridian: 6 County: LARIMER Field Name: Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: WELLINGTON OPERATING COMPANY Agent Name: Randy Evans Title: Wastewater Treatment ORC Phone Number: 970-402-0418 Email: Revans@Wellingtonoperating.com

Rule 909.J Inspection Information

Date the Pit was Inspected On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 468761 Facility Name: Injection Plant 1 Facility Type: Oil/Gas Production Facility Location: QtrQtr: NESW Sec: 15 Twp: 9N Range: 68W Meridian: 6 County Name: LARIMER Latitude: 40.746010 Longitude: -104.990410

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 121127 Document Name: CLMSS Unit Produced Water Rad 202405 File Name: L1738116 RRE.xlsx Sample Type: Matrix: Facility ID: 468761 Sample ID: 660837 Sample Name: CLMSS Unit Produced Water 202405 Sample Date: 05/16/2024 Collection Point: Tank Matrix: WATER Pre Post: Rule 909.j initial sample Project Number: 10693414 Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Pace Analytical Lab Sample ID: L1738116-01

Batch ID: 122662 Document Name: CLMSS Produced Water 202405 Update File Name: 10693414 RRE Update.xlsx

SampleType: _____ Matrix: _____

Facility ID: 468761 Sample ID: 662492 Sample Name: CLMSS Unit Produced Water 202405 Sample Date: 05/16/2024

Collection Point: Tank Matrix: WATER Pre Post: Rule 909.j initial sample

Project Number: 10693414 Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Pace Analytical Lab Sample ID: 1069341400
1

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
468761	403942481	10693414_frc.pdf	Analytical Laboratory Report	PDF
468761	403942482	10693414_frc.pdf	Analytical Laboratory Report	PDF

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

User Group	Comment	Comment Date
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	10/15/2024
Environmental Data	RTD due to incomplete 909j analytical suite.	09/17/2024
Total: 2 comment(s)		