

Inspection Photos
Location Name:UPRR 23 PAN AM M #3
Location ID: 320062



Photo #1 Tanks (weeds on, in berm and throughout location)



Photo #2 Vault (weeds on, in berm and throughout location)

Inspection Photos
Location Name:UPRR 23 PAN AM M #3
Location ID: 320062



Photo #3 Unused separator. (weeds throughout location).



Photo #4 Meter run & unmarked risers. (weeds throughout location).

Inspection Photos
Location Name:UPRR 23 PAN AM M #3
Location ID: 320062



Photo #5 Well head (weeds throughout location).