

North Shore Exploration and Production LLC
Smith 1
Location ID: 313052



Staining outside of tank berm



Staining outside of tank berm

North Shore Exploration and Production LLC
Smith 1
Location ID: 313052




Open end load line



Valve plug on the ground

North Shore Exploration and Production LLC
Smith 1
Location ID: 313052



Staining



Staining

**North Shore Exploration and Production LLC
Smith 1
Location ID: 313052**




Staining



Staining from hose dragging

North Shore Exploration and Production LLC
Smith 1
Location ID: 313052



Staining



Staining

North Shore Exploration and Production LLC Smith 1 Location ID: 313052

6/23 10:27 AM

Calibration Report

Report Date: 6/23/23 Collection Time: 6/23 10:27 AM

Section 1: SMITH 1 System: ABB TOTALFLOW

Device ID: Smith 1-35 Field: CO

Location: 0 State: North Shore

FMP: Purchaser:

Company Name: 16/23

Calibration Date: 6/23

Station: 2-5-11P Flange: Specific Gravity: 0.8

Current Plate Size: 2.067 Up Stream: 14.73 Temperature Bias: 0

Atmos. Pressure: 11.7 Dirty? Warped? Bevel Downstream? No

Plate Inspected? Dirty Mkt'd Pitted No

Edge Sharp? No

Edge Rupt. Damaged? No

Standard: 3 DP check with pressure on SP: No

DIFFERENTIAL		FOUND		LEFT	
Test	Meter	Test	Meter	Test	Meter
1	0.0380	0.0000	0.0380		
2	250.0370	250.0000	250.0370		
3	187.5000	187.5040	187.5000		
4	125.0000	125.0350	125.0000		
5	62.5000	62.5000	62.5000		
6	0.0000	0.0150	0.0000		
7			0.0780		

STATIC PRESSURE		FOUND		TEMPERATURE	
Test	Meter	Test	Meter	Test	Meter
1	11.7000	11.7000	11.7020		
2	51.7000	51.7000	51.8730		
3	35.7000	35.7000	35.7000		
4	28.7000	28.7000	28.7130		
5	13.7000	13.7000	13.6730		
6	11.7000	11.7230	11.7230		

Gas Sample Taken: Yes No H2S analysis done: Yes No

PPI: 6.7% H2O Analysis Done: Yes No

REMARKS:

Signature / Company: Thomas Stoitt

Calibrated by: Thomas Stoitt

Witness:

Oct 15, 2024 at 4:12:56 PM



Well gas meter calibration overdue

Relief vent riser missing cap

North Shore Exploration and Production LLC
Smith 1
Location ID: 313052



Staining



Debris

North Shore Exploration and Production LLC
Smith 1
Location ID: 313052




Debris



Debris

North Shore Exploration and Production LLC
Smith 1
Location ID: 313052



Staining. Debris.



Debris

North Shore Exploration and Production LLC
Smith 1
Location ID: 313052



Debris



Open to wildlife

**North Shore Exploration and Production LLC
Smith 1
Location ID: 313052**





Drain pail from 11/8/23



Drain pail still open to wildlife

North Shore Exploration and Production LLC
 Smith 1
 Location ID: 313052



Gas meter calibration card from 11/8/23

Gas meter calibration still overdue

**North Shore Exploration and Production LLC
Smith 1
Location ID: 313052**



Location from Southeast corner

Location from Northeast corner

**North Shore Exploration and Production LLC
Smith 1
Location ID: 313052**



Location from Northwest corner



Location from Southwest corner