

Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: ANDY'S MESA UNIT #10-E28

Location ID: 316805

API #: 05-113-06023

Inspection Date: 10/10/2024 Inspection Doc#: 693807843



Wellhead with fence



Separator and Meter housing

Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: ANDY'S MESA UNIT #10-E28

Location ID: 316805

API #: 05-113-06023

Inspection Date: 10/10/2024

Inspection Doc#: 693807843



Tank battery



Location overview looking SE