

Final Reclamation and Stormwater Inspection

October 10, 2024

Operator: KERR MCGEE OIL & GAS ONSHORE LP - #47120

Location ID: 329141

Inspection Document #: 697505514

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-VADMAN-63N66W 34NENW
Location ID: 329141



Photo 1. Photo taken from the entrance of the off-location tank battery, facing South. Photo illustrates final reclamation activities have been performed; however, a midstream meter house remains.



Photo 2. Photo taken from the entrance of the off-location tank battery, facing West. See comments under Photo 1.

Inspection Photos

Location Name: HSR-VADMAN-63N66W 34NENW

Location ID: 329141



Photo 3. Photo taken along a portion of the access road, facing South. Photo illustrates much of the access road within the tire track portions did not have any germination or straw mulch.



Photo 4. Photo taken along a portion of the access road along the eastern side. Photo illustrates germination of plant species within the straw mulch.



Inspection Photos

Location Name: HSR-VADMAN-63N66W 34NENW

Location ID: 329141



Photo 5. Photo taken from the well location, facing East. Photo illustrates the well location is predominately weedy, annual vegetation.



Photo 6. Photo taken from the well location, facing North. See comments under Photo 5.



Inspection Photos

Location Name: HSR-VADMAN-63N66W 34NENW

Location ID: 329141



Photo 7. Photo taken from the well location, facing South. See comments under Photo 5.



Photo 8. Reference photo taken west of the well location, facing North.

