

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, HOAGLUND-66S95W/35SESE

Location ID: 334762

Date: 10/15/2024



North End of Location – Photo #04190



Wellheads – Photo #04191

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, HOAGLUND-66S95W/35SESE

Location ID: 334762

Date: 10/15/2024



Oct 15, 2024 at 10:35:08

Separators – Photo #04193



Oct 15, 2024 at 10:35:28  
Parachute CO 81635  
United States

Tank Battery – Photo #04194