

Final Reclamation Inspection

September 19, 2024

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 305875

Inspection Document #: 697505518

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BETZ #30-15
Location ID: 305875



Photo 1. Photo taken from a southern portion of the access road, facing Southeast. Photo illustrates Operator has completed repair road damages by importing surface owner approved gravel.



Photo 2. Photo taken from a southern portion of the access road, facing Northwest. See comments under Photo 1.

Inspection Photos
Location Name: BETZ #30-15
Location ID: 305875



Photo 3. Photo taken from a central portion of the access road, facing Northwest. Photo illustrates Operator has completed repair road damages by importing surface owner approved gravel and seeded/straw crimped mulch to reduce road surface disturbances.



Inspection Photos
Location Name: BETZ #30-15
Location ID: 305875



Photo 4. Photo taken from a northern portion of the access road, facing Northwest. See comments under Photo 1.



Photo 5. Photo taken from a northern portion of the access road, facing Southeast. See comments under Photo 1.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 697505518