

Inspection Photos
Location Name: CECIL USX AB-67N64W/35SESW
Location #: 302231



Photo #1

Cecil USX AB 35-14 (123-27389) Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: 2ndary plugs



Photo #2

Cecil USX AB 35-14 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: 2ndary plugs
Site safety signage



Inspection Photos

Location Name: CECIL USX AB-67N64W/35SESW
Location #: 302231



Photo #3
Cecil USX AB 35-14 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: 2ndary plugs
Wellsite entrance




Photo #4
Cecil USX AB 35-14 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: 2ndary plugs
JSA: 2024-10-14

