

State of Colorado  
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

## ECMC RECEPTION

Receive Date:

02/12/2024

Document Number:

403683983

## ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

**Operator Information**

ECMC Operator Number: 47120 Contact Person: Erik Mickelson  
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (970) 929-4306  
Address: P O BOX 173779 Fax: ( )  
City: DENVER State: CO Zip: 80217-3779 Email: Erik\_Mickelson@oxy.com

**Identification Information**

API Number: 05 - - ECMC Facility ID: 485209 Initial Form 19 or 27 Document number:  
Facility Name: LIZZY Facility Number: 8-36HZ Facility Type: LOCATION  
Location QtrQtr: SENE Section: 36 Township: 1N Range: 68W Meridian: 6  
County: WELD Field Name:  
Federal, Indian or State Lease Number:

## Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional  
Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

## Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 753446 Facility Name: Beltran 132959 Facility Type: Domestic Well  
Location: QtrQtr: NENW Sec: 6 Twp: 1S Range: 67W Meridian: 6  
County Name: ADAMS Latitude: 39.999030 Longitude: -104.934550

**Sample Information:**

The following Sample Information has been reviewed by the ECMC:

Batch ID: 117020 Document Name: Size of file in bytes: 77824 File Name: 2023\_11\_09\_Beltran 132959 SGS ECMC.xls  
SampleType: Matrix:  
Facility ID: 753446 Sample ID: 656365 Sample Name: Beltran 132959 Sample Date: 11/09/2023  
Collection Point: Dom Matrix: WATER Pre Post: Voluntary baseline sample  
Project Number: Remediation Number: Complaint Number: NOAV Number:  
Inspection Number: Spill Number: Laboratory: Accutest Lab Sample ID: DA59952-1

Batch ID: 117018		Document Name: Size of file in bytes: 35840		File Name: 2023_11_09_Beltran 132959 Isotech NG4 ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 753446	Sample ID: 656363	Sample Name: Beltran 132959		Sample Date: 11/09/2023	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary baseline sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 898153		

  

Batch ID: 117018		Document Name: Size of file in bytes: 35840		File Name: 2023_11_09_Beltran 132959 Isotech NG4 ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 753446	Sample ID: 656362	Sample Name: Beltran 132959		Sample Date: 11/09/2023	
Collection Point: Dom	Matrix: GAS	Pre Post: Voluntary baseline sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 898153		

  

Batch ID: 117021		Document Name: Size of file in bytes: 31744		File Name: 2023_11_09_Beltran 132959 Trip Blank SGS ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 753446	Sample ID: 656366	Sample Name: Beltran 132959		Sample Date: 11/09/2023	
Collection Point: TB	Matrix: WATER	Pre Post: Voluntary baseline sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA59953-1		

  

Batch ID: 117019		Document Name: Size of file in bytes: 25600		File Name: 2023_11_09_Beltran 132959 SGS ECMC DRO.xls	
SampleType: _____			Matrix: _____		
Facility ID: 753446	Sample ID: 656364	Sample Name: Beltran 132959		Sample Date: 11/09/2023	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary baseline sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA59952-1		

**Sample Facility Attachment:**

Facility ID	Attach Num	File Name	Document Name	File Type
753446	403683985	2023_11_09_Beltran 132959 Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
753446	403684004	2023_11_09_Beltran_132959_Wellhead_Loc.jpg	Photographs	JPG
753446	403684007	2023_11_09_Beltran_132959_PrePostPurge.jpg	Photographs	JPG
753446	403683994	2023_11_09_Beltran_132959_Spigit.jpg	Photographs	JPG
753446	403683995	2023_11_09_Beltran_132959_Spigit_Loc.jpg	Photographs	JPG
753446	403683993	2023_11_09_Beltran_132959_FS_ECMC.pdf	Field Data Report	PDF
753446	403683990	2023_11_09_Beltran 132959 SGS.pdf	Analytical Laboratory Report	PDF
753446	403683988	2023_11_09_Beltran 132959 Isotech NG4.pdf	Analytical Laboratory Report	PDF
753446	403683998	2023_11_09_Beltran_132959_Wellhead.jpg	Photographs	JPG

**Sample ECMC Well Related:**

No Sample ECMC Well Related Information Provided.

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	10/16/2024
Total: 1 comment(s)		