

Inspection Photos

October 15th, 2024

Operator: Logos Operating - 10679

Location ID: 326449

Inspection Document #: 714001352

La Plata County, CO

Township: NWN 12 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ignacio 33-8 001C
Location ID: 326449

10/15/24
200° S



Photo 1. View of the well pad taken from the access point facing center.



API #: 067-08119

Inspection Photos
Location Name: Ignacio 33-8 001C
Location ID: 326449



Photo 2. Animal burrow impacting produced water tank secondary containment.

Inspection Photos
Location Name: Ignacio 33-8 001C
Location ID: 326449

10/15/24
218° SW



Photo 3. View of western interim reclamation area composed predominantly of Intermediate Wheatgrass.

Inspection Photos
Location Name: Ignacio 33-8 001C
Location ID: 326449

10/15/24
233° SW



Photo 4. Reference area composed of Intermediate Wheatgrass and Smooth Brome.