

Inspection Photos

October 15th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326656

Inspection Document #: 714001353

La Plata County, CO

Township: SENE 12 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Tillman Burch 2
Location ID: 326656



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: Tillman Burch 2
Location ID: 326656



Photo 2. View of weedy Kochia debris on the center of the active pad and lining the southern edges.

Inspection Photos
Location Name: Tillman Burch 2
Location ID: 326656

10/15/24
320° NW



Photo 3. View of western interim reclamation area composed predominantly of Intermediate Wheatgrass.

Inspection Photos
Location Name: Tillman Burch 2
Location ID: 326656

10/15/24
342° N



Photo 4. Reference area composed of Intermediate Wheatgrass and Sagebrush.