

# Inspection Photos

October 15th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306814

Inspection Document #: 714001356

La Plata County, CO

Township: NWSE 7 33N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Lucero 2  
Location ID: 306814

10/15/24  
4° N



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos  
Location Name: Lucero 2  
Location ID: 306814

10/15/24  
272° W



**Photo 2.** Large patch of weedy Kochia debris observed at the access point.

Inspection Photos  
Location Name: Lucero 2  
Location ID: 306814

10/15/24  
358° N



**Photo 3.** View of western interim reclamation area composed predominantly of Intermediate Wheatgrass.

Inspection Photos  
Location Name: Lucero 2  
Location ID: 306814

10/15/24  
203° SW

