

# Inspection Photos

October 15th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325787

Inspection Document #: 714001357

La Plata County, CO

Township: SESE 7 33N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Lucero 1  
Location ID: 325787

10/15/24  
61° NE



**Photo 1.** View of the well pad taken from the access point facing center.



API #: 067-06983



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Lucero 1  
Location ID: 325787



**Photo 2.** View of the eastern and western interim reclamation areas, composed predominantly of Smooth Brome and Rubber Rabbitbrush.



Inspection Photos  
Location Name: Lucero 1  
Location ID: 325787

10/15/24  
170° S



**Photo 3.** Irrigated pasture field reference area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06983