

# Inspection Photos

October 15th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306811

Inspection Document #: 714001358

La Plata County, CO

Township: NENW 18 33N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Ute AC 2  
Location ID: 306811



Photo 1. View of the well pad taken from the access point facing center.





Inspection Photos  
Location Name: Ute AC 2  
Location ID: 306811

10/15/24  
186° S



**Photo 2.** View of the western interim reclamation area dominantly by Yellow Hoary Aster, Smooth Brome and Sand Dropseed.



Inspection Photos  
Location Name: Ute AC 2  
Location ID: 306811



10/15/24  
215° SW

**Photo 3.** View of stormwater BMPs installed in the western portion of the disturbance. Erosion appears to be controlled at this time.



Inspection Photos  
Location Name: Ute AC 2  
Location ID: 306811

10/15/24  
199° S



**Photo 4.** View of reference area composed of Sagebrush, Juniper and James Galleta.