

Inspection Photos

October 15th, 2024

Operator: Arkoma Operations - 10766

Location ID: 311910

Inspection Document #: 714001360

La Plata County, CO

Township: NWSW 18 33N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ute, Ige
Location ID: 311910



Photo 1. View of the multi well pad taken from the access point facing center.

Inspection Photos
Location Name: Ute, Ige
Location ID: 311910

10/15/24
309° NW



Photo 2. View of the northern interim reclamation area composed of Smooth Brome, Western Wheatgrass and Prairie Sunflower.

Inspection Photos
Location Name: Ute, Ige
Location ID: 311910



Photo 3. Impacted surface material observed at the Ige 118 well head.

Inspection Photos
Location Name: Ute, Ige
Location ID: 311910

10/15/24
63° NE



Photo 4. Reference area composed of Sagebrush and Smooth Brome.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: Multi Well Pad