

Inspection Photos  
Location Name: WEIGANDT.JOHN H.#A-1  
Location ID: 320238



Photo#1 **CA: Access road vegetation not controlled**

Photo#2 Pumpjack/**CA:Weeds/Debris**