

Final Reclamation and Stormwater Inspection

Date: 10/16/2024

Operator: CRESTONE PEAK RESOURCES OPERATING
LLC - 10633

Location ID: 466610

Inspection Document #: 708201705

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Lochbuie Facility
Location ID: 466610



Photo 1. Facing northwest. Operator has performed final reclamation activities by removing all equipment from location. ECMC Staff did not perform a compaction test. The tank battery location is within recently harvested/fallow cropland; therefore, a future inspection will be conducted during the active crop growing season to ensure vegetative compliance.

Inspection Photos
Location Name: Lochbuie Facility
Location ID: 466610



Photo 2. Facing southeast; see comments in Photo 1.

Inspection Photos
Location Name: Lochbuie Facility
Location ID: 466610



Photo 3. Facing north; see comments in Photo 1.